



HYDRO-MULCHER[®]



Winterization Information!

A few pointers:

- Clean entire machine before storage. Clean inside of tank and drain. Scraped, scratched and bare metal surfaces repaint (Bowie green *Sherwin-Williams* #F75GT5, Tile Clad Safety Red Epoxy *Sherwin-Williams* #B62R38, Tile Clad Epoxy Hardener *Sherwin-Williams* #B60V70)
- On Centrifugal Pumps: remove drain plug in bottom of pump. Bowie Gear Pumps: grease each fitting with 15 pumps of grease. Turn pump slowly a few revolutions.
- All ball and gate valves open half way
- Add *Sta-Bil* fuel stabilizer to fuel tank (prevents fuel deterioration, makes starting easier). Run engine for 15 minutes.
- Water-cooled engines be sure radiator has proper amount of anti-freeze.
- Remove battery and store indoors.
- Drain filter on filter-regulator of Horton Air Clutch (1500, 2500, 3000 Models)
- Spray WD-40 on Formsprag Clutches (500, 600, 800, 1100 Models)
- Grease all fittings, spray *Chemsearch Lubrease* or equivalent (which penetrates and protects from corrosion) on all roller chain.

Send me future factory bulletins.

Name _____

Address _____

City _____ State _____ Zip _____ Phone _____

Model No. _____ Serial No. _____

Bowie Industries, Inc
PO Box 931, Bowie, Texas 76230
Phone 800.433.0934 FAX 940.872.4792 E-mail info@bowieindustries.com
Hours 8 AM to 5 PM Central Time Zone

